Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1193Work Order Type: WeatherizationAudit Name: 14014SO1193

CLIENT INFORMATION

Client Name: 14014SO1193 Address: , Unit 1099

Client ID: 14014SO1193 Hampshire, TN 38461

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO1193 Applicant/Person of Record ✓

<u>AGENCY INFORMATION</u>

Agency: South Central Human Resource Agency

Agency Phone: (931) 433-7182

Address: 1437 Winchester Highway Fax: (931) 438-0074

Fayetteville, TN 37334 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Mobile home in good cond. Replace HVAC System and DWH

Client Name: 14014SO1193 Client ID: 14014SO1193 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO1193
Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 6

Measures

	Measure 1 Gen	eral Air Sealing		Components					Inspected
C	2. Repa 3. Foan 4. Foan	ic return air plenum. iir multiple holes in walls. n plumbing intrusions. n intrusions around wash iir floor in DWH		er.					
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Supplies	Infiltration Reduction	Each	1					
2	Labor	Labor	Hour	4					
	Other Detail								
			ı	Measure	e Sub Total:] ;	Sub Total:	
	Field Notes:								
		lace HVAC sytem			Componen		Syster		Inspected
C	Measure 2 Rep	•			Estimated	<u> </u>		Actual	
C	Measure 2 Rep Comment Material / Labor	Description / Comment	Units	Qty	•		Syster		Inspected Total
C	Measure 2 Rep	•	<i>Units</i> Each		Estimated	<u> </u>		Actual	
C #	Measure 2 Rep comment Material / Labor Heating	Description / Comment		Qty	Estimated	<u> </u>		Actual	
c # 1	Measure 2 Rep comment Material / Labor Heating Equipment	Description / Comment HVAC System	Each	Qty 1	Estimated	<u> </u>		Actual	
c # 1	Measure 2 Rep comment Material / Labor Heating Equipment Labor	Description / Comment HVAC System	Each	Qty 1	Estimated	<u> </u>		Actual	
c # 1	Measure 2 Rep comment Material / Labor Heating Equipment Labor	Description / Comment HVAC System	Each	Qty 1 1	Estimated Unit Cost	<u> </u>	Qty	Actual	
c # 1	Measure 2 Rep comment Material / Labor Heating Equipment Labor	Description / Comment HVAC System	Each	Qty 1 1	Estimated	<u> </u>	Qty	Actual Unit Cost	
c # 1	Measure 2 Report Material / Labor Heating Equipment Labor Other Detail	Description / Comment HVAC System	Each	Qty 1 1	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	
C # 1	Measure 2 Report Material / Labor Heating Equipment Labor Other Detail	Description / Comment HVAC System	Each	Qty 1 1	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	

Client Name: 14014SO1193 Client ID: 14014SO1193 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO1193

DOE Weatherization Assistant Version 8.5.0

Page 2 of 6

Report Run On: 5/28/2010

Measure 3 DWH Pipe Insulation					Componen		Inspected		
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DWH Pipe Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:								

Measure 4 Rep	alce DWH			Componen	ts DWH			Inspected	
Comment									
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DWH	Each	1						
	Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide								
2 Labor	Labor	Each	1						
Other Detail									
			Measur	re Sub Total:			Sub Total:		
Measure 5 Rep	lace Front Door Unit, W	S, DS, Lo	ck	Componen			Actual	Inspected	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Doors	Replace Front Door Unit, WS, DS, Lock	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
			Measur	re Sub Total:			Sub Total:		
Field Notes:				L		1	L		

Client Name: 14014SO1193 Client ID: 14014SO1193 Alt. Client ID: Maury DOE Weatherization Assistant Version 8.5.0 Page 4 of 6

Report Run On: 5/28/2010

Comment	Cool S	Seal Roof			Componen	ts Roof			Inspected
					Estimated	<u> </u>		Actual	
# Material / Lab	oor L	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	(Cool Seal Roof	Each	1					
2 Labor	L	_abor	Hour	3					
Other Detail							1 [
				Measur	e Sub Total:			Sub Total:	
Measure 7 Comment	Fix Im	proper Venting (Cloti	nes Drver	•	<u></u>				
				,	Componen		ıg		Inspected
			•		Estimated	1		Actual	
		Description / Comment Equipment	<i>Units</i> Each	Qty 1	•		Qty		Inspected Total
1 Health and S Items	Safety E	Description / Comment	Units	Qty	Estimated	1		Actual	
1 Health and S Items	Safety E	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1		Actual	
2 Labor	Safety E	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1		Actual	
1 Health and S Items2 Labor	Safety E	Description / Comment Equipment	Units Each Hour	Qty 1 0.5	Estimated	1	Qty	Actual	

Measure 8 Smoke/ CO2 Detector Combo				Componen	ts H&S	Inspecte			
C	Comment								
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke/CO2 Detector Combo	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail						1		
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
			Work Or	der Gra	nd Total:		Gran	d Total:	